

1

**COOCH BEHAR** ('D' CLASS)

**(COB)**

UP →



BXT END →

← NCB END

### DEWANHAT 'B' CLASS/STD.-II(R)/PI

CH.-37125.68 FROM APDJ

UP →



3

**BHETAGURI** (^D' CLASS)

**(VTG)**

UP →

BXT END →

← NCB END

**DINHATA COLLEGE HALT** ('D' CLASS)

**(DCH)**

UP →



BXT END →

← NCB END

### DINHATA ('B' CLASS/STD.-II(R)/EI)

CH.-49899.85 FROM APDJ

UP →



6

**FALIMARA** ('D' CLASS)

**(FLM)**

UP →

BXT END →

← NCB END

7

**NEW GITALDAHA** ('D' CLASS)  
**(NGTG)**

UP →

BXT END →

← NCB END

8

**ABUTARA** ('D' CLASS)

**(ABW)**

UP →

BXT END →


← NCB END



### BAMANHAT 'C' CLASS/STD.-I(R)/PI

CH.-72341.30 FROM APDJ

UP →



EMERGENCY KEY (CHAINED WITH GATE CRANK HANDLE) ELECTRICALLY INTERLOCKED WITH CONCERNED SIGNALS FOR L.C. GATE NO. AB/62 IN GLASS FRONTED CASE AT S.B. (SEALED & PAD LOCKED)

